TASCAM FW-1884/1804/1082 Release Notes

Contents

Updates	. 1
Maintenance Items	. 1
Windows Driver	1

Updates

Always use the most recent firmware for this device. Please visit the TASCAM web site at http://www.tascam.com to check for the latest firmware.

Maintenance items

Windows Driver

V1.70 changes

On computers running the 64-bit version of Windows Vista with more than 2 GB of RAM installed, there had been noise in audio input and output over firewire when using audio applications. This has been fixed in 1.70.

Windows driver: 1.70